

Technical Bulletin

K1990 2 Loop Addressable Hochiki HRE Protocol Control Panels

TB 1005

We regret to announce that the processor and printer mechanism for the B1920 printer on this range of control panels have both recently become obsolete.

Whilst we are committed to supporting all of our products for as long as we can and have been holding small stocks of replacement parts for these items, these are now exhausted and can no longer be sourced.

Printers for these panels can therefore no longer be manufactured or repaired.

Printers for Signifire, Solo and Syncro control panels are not effected by this component shortage and remain readily available.